



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	88	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	7	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5800		Narcissus	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0006.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 88

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\88.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	89	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3603		Menlo	DR

Source Type:	12= MH Frame Seal	Location:	2=Paved Asphalt	Severity:
---------------------	-------------------	------------------	-----------------	------------------

Sector:	1=Public	Drainage Area:	2600
----------------	----------	-----------------------	------

Comments: main hole smaller lead

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_A\A_2004_0831Image0005.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

89

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\89.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	89	Date:	8/31/2004	MeterBasin:	01_WR23
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3608		Menlo	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0007.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

89

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\89.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	89	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3607		Menlo	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	200	

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 8

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0008.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

89

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\89.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	89	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3605		Menlo	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	50	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0009.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No:

89

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\89.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	90	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3808		Menlo	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_A\A_2004_0831Image0006.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 90

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\90.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	90	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3811		Menlo	DR

Source Type:	18= Other	Location:	8=Yard-Back	Severity:
Sector:	2=Private	Drainage Area:	50	

Comments: Alley - hole in ground could be service or main

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_A\A_2004_0831Image0007.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 90

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\90.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	90	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3714		Menlo	DR

Source Type:	02= Service Line	Location:	5=Sidewalk	Severity:
Sector:	1=Public	Drainage Area:	25	
Comments:	crack in sidewalk			

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0010.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 90

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\90.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	90	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3706		Menlo	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	125	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0011.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 90

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\90.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	90	Date:	8/31/2004	MeterBasin:	01_WR23
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3702		Menlo	DR

Source Type:	04= Cleanout	Location:	5=Sidewalk	Severity:
---------------------	--------------	------------------	------------	------------------

Sector:	2=Private	Drainage Area:	150
----------------	-----------	-----------------------	-----

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0012.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 90

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\90.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	90	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3712		Glen	AVE

Source Type:	04= Cleanout	Location:	12=Alley	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0013.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 90

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\90.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	90	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3708		Glen	AVE

Source Type:	04= Cleanout	Location:	9=Yard-Side	Severity:
---------------------	--------------	------------------	-------------	------------------

Sector:	2=Private	Drainage Area:	100
----------------	-----------	-----------------------	-----

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0014.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 90

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\90.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	90	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3704		Glen	AVE

Source Type:	04= Cleanout	Location:	9=Yard-Side	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments: drainage cannot be determined

SMOKE TEST PHOTOS



Photo No:
Filename Path:

Image Status: No image name specified.

Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0015.JPG

Image Status: Image found and displayed.

Photo No:
Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 90

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\90.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	90	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	7	Setup No:	3	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3713		Menlo	DR

Source Type:	04= Cleanout	Location:	9=Yard-Side	Severity:
Sector:	2=Private	Drainage Area:	200	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0016.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 90

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\90.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	91	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6101		Hopeton	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_A\A_2004_0831Image0009.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 91

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\91.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	91	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6103		Hopeton	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_A\A_2004_0831Image0010.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 91

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\91.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	91	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3810		Pinkney	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_A\A_2004_0831Image0011.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 91

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\91.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	91	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6205		Hopeton	AVE

Source Type:	02= Service Line	Location:	5=Sidewalk	Severity:
Sector:	1=Public	Drainage Area:	25	

Comments: crack in sidewalk

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0017.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 91

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\91.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	91	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	4	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6205		Hopeton	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments: drainage cannot be determined

SMOKE TEST PHOTOS




Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0018.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 91

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\91.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	91	Date:	8/31/2004	MeterBasin:	03_31S
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	4	Priority CCTV:	

House Number	3808	Street Prefix:		Street Name:	Pinkney	Street Type:	ROAD
Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:			
Sector:	2=Private	Drainage Area:	25				
Comments:	hole in ground						

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\0831-2004\T-1\PLAYER_B\B_2004_0831Image0019.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 91

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\91.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.